



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division Board of Directors



# Temperature Measurement 2

Modified on Sunday, 01 February 2015 10:14 PM by [mpieler](#) Categorized as [Extrusion Hints](#) (10) » [Vent Openings](#) » [Zone Cooling Check Up](#) » **Temperature Measurement 2** 


Temperature measurement 2  
Vol.20 #3, Dec. 1993

To get truest process temperature control, locate barrel thermocouples in the area where the screw is 100% full, or over mixing elements.

See also:

- [Barrel thermocouple maintenance](#)
- [Seated TCs](#)
- [Temperature control](#)
- [Temperature measurement 1](#)
- [Thermocouples](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .