



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Improved Dies

Modified on Sunday, 01 February 2015 11:28 PM by [mpieler](#) Categorized as [Extrusion Hints](#)   
(10) » [Purge Material](#) » [Stripping Vent Help](#) » [Improved Dies](#)

Improved dies  
Vol. 23 #1, May 1996


Die plate out or carbon build up can cause die lines and contamination of sheet products.

During the last several years, several die manufactures are offering low surface energy die treatments which mimics the effect of flouropolymer additives for polyethylene, as well as improves die cleanliness.

See also:

- [Die and screw cleaning](#)
- [Gels 3](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .