



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



DC Drive Failure

Modified on Sunday, 01 February 2015 11:55 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Startup Timers](#) » [Vent Flow](#) » **DC Drive Failure**

DC drive failure
Vol. 24 #1, March 1997

The sudden appearance of high frequency vibration on an extruder can result from various causes, but one of the most common, but most difficult to diagnose, is a DC drive controller failure where one SCR fails or misfires, creating a chopped, or pulsed, output to the motor.


This condition often requires a scope and a trained drives technician to diagnose.

- Bill Kramer, American Kuhne Corp.

See also:

- [Broken couplings](#)
- [Brush wear forecasting](#)
- [Drive motor start up](#)
- [Power factor](#)
- [Threaded commutators](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .