



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki



Viewing /Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



powered by
screwturn wiki

Insulate Vent

Modified on Monday, 02 February 2015 12:27 AM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Bolt Cleaning](#) » [Color Changes](#) » [Insulate Vent](#)

Insulate Vent
Vol. 24 #3, Dec. 1997

Insulation, and/or even heating, of vacuum ports can be helpful to prevent condensation of ingredients being pulled out of polymer melt that could ultimately plug the port.

- Bill Corcoran, Dupont Co.

See also:

- [Vent design](#)
- [Vent flow](#)
- [Vent insert design](#)
- [Vent openings](#)
- [Vent plugging](#)
- [Vents 1](#)
- [Vents 2](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .