



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration

- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Corona Treatment

Modified on Monday, 02 February 2015 01:09 PM by [mpieler](#) Categorized as [Extrusion Hints](#)

[\(10\)](#) » [Checking Extrusion Output Rates Without the Use of a Calculator](#) » [Profile Die Design](#) » [Corona Treatment](#)

Corona treatment  
Vol. 27 #1, March 2000


Corona treatment is a method of oxidizing a film surface by generating free radicals on a film surface by electron bombardment and ozone generation in the treater gap. Because of this chemistry, the surface can be degraded giving low molecular weight and weak surfaces. This leads to lower ink or lamination bond strengths even though the treatment level has increased, i.e., you can overtreat.

- Eldridge Mount, Mobil Chemical Co.

See also:

- [Corona treater power](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .