



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Output Variation 2

Modified on Sunday, 01 February 2015 04:57 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Twin Screw Color Change](#) » [Accurate Melt Temperature](#) » **Output Variation 2**


Output Variation 2
Vol. 17 #3, Dec. 1990

In the July 1990 Extrusion Hints, there was an error in the formula for calculating the effect of pressure changes on product variation (see Output variation 1). The correct formula, with an example calculation, is in the Consultants Corner article by Chris Rauwendaal (The Effect of Pressure on Output, Consultants Corner, Vol. 17 #3, December 1990).

See also:

- [Melt pressure](#)
- [Melt pressure indicator](#)
- [Output calculations](#)
- [Output rates](#)
- [Output rate check](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .