



## Navigation



### Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

### Search the Wiki

  »

### Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

### Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

### Administration

- [Administration](#)
- [File Management](#)

### Brought to you by:

The SPE Extrusion Division Board of Directors



# Melt Delivery

Modified on Monday, 02 February 2015 12:23 AM by [mpieler](#) Categorized as [Extrusion Hints](#) 

Melt Delivery  
Vol. 24 #3, Dec. 1997

Let's not forget that melt delivery in injection molding operations is based on extrusion.


All those factors affecting good melt quality in extrusion impact injection molding similarly.

- Ken Powell, Becton Dickinson Research Center

See also:

- [Extrusion trials](#)
- [Improve melt quality](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .