



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Monitor Back Pressure

Modified on Monday, 02 February 2015 12:26 AM by [mpieler](#) Categorized as [Extrusion Hints](#) 

[\(10\)](#) » [Mold release](#) » [Feed Stock Supply](#) » [Monitor Back Pressure](#)

Monitor Back Pressure
Vol. 24 #3, Dec. 1997

Monitoring extruder back pressure is critical to understanding if the process is in control.


It is important to validate, through the use of statistics, to identify the mean and, equally important, the variation (or standard deviation) to within 1% of set point.

- Daniel Cykana, Bemis Manufacturing Co.

See also:

- [Metering pump](#)
- [Restrictive adapter](#)
- [Rules of thumb](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .