



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration

- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Unmixed Polymer Gels

Modified on Monday, 02 February 2015 01:01 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 

(10) » [Color Marker](#) » [Pull the Screw](#) » [Unmixed Polymer Gels](#)

Unmixed Polymer Gels

Vol. 26 #2, September 1999 and Vol. 26 #3, December 1999


Unmixed polymer gels are defects in film quality that are produced in the extruder when inadequate mixing/melting occurs. These gels are not degraded polymer, but discrete domains of polymer at a lower temperature than the bulk melt. Both screw design and process conditions can be the cause of unmixed gels. With regard to screw design, a transition section that is too short can produce unmixed gels in films. These screws will also have more tendency to exhibit surging problems. Polymers that melt too early in the screw can also disrupt the solids bed and produce unmixed gels.

- Tom Butler, Dow Chemical Co.

See also:

- [Gels 1](#)
- [Gels 2](#)
- [Gels 3](#)
- [Gel identification](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .