



Navigation



Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

Search the Wiki

  »

Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

Administration


- [Administration](#)
- [File Management](#)

Brought to you by:

The SPE Extrusion Division
Board of Directors



Interactions

Modified on Monday, 02 February 2015 01:13 PM by [mpieler](#) Categorized as [Extrusion Hints](#) 
(10) » [Removing Polymer Melt](#) » [Dehumidifying Dryers](#) » **Interactions**

Interactions

Vol. 27 #2, November 2000


Interaction effects on the extrusion process are tied to many things, with one example being material feed properties. Such things as moisture content and particle size can and do impact the feed accuracy of ingredients which in turn affect product properties. Therefore, care must always be given to the quality and condition of feed ingredients.

- Bill Corcoran, Dupont Co.

See also:

- [Avoid feed stock fluidization](#)
- [Feed rate limited](#)
- [Feed stock supply](#)

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .