



## Navigation



## Extrusion 1-0-Wiki Pages

- [Main Page](#)
- [Best Papers](#)
- [Book Reviews](#)
- [Consultants Corner](#)
- [Extruder Software](#)
- [Extrusion Hints](#)
- [Safety](#)
- [Shop Tools](#)
- [Sponsors](#)
- [Technical Articles](#)

## Search the Wiki

  »

## Viewing/Creating

- [Random Page](#)
- [Create a new Page](#)
- [All Pages](#)
- [Categories](#)

## Account Management

- [Login/Logout](#)
- [Language Selection](#)
- [Your Profile](#)
- [Create Account](#)

## Administration


- [Administration](#)
- [File Management](#)

## Brought to you by:

The SPE Extrusion Division  
Board of Directors



# Reduce Temperature Variation


Modified on Thursday, 26 February 2015 04:05 PM by [mpieler](#) Categorized as [Extrusion Hints](#)   
(10) » [Crystalline Structure](#) » [Purging Compounds](#) » [Reduce Temperature Variation](#)

Reduce Temperature Variation  
Vol. 33 #1, Summer 2006

Thermal uniformity of melt entering the die is critical to maintaining uniform die performance and gauge control for a typical single screw extrusion operation there is a 15°F to 40°F difference between product skin and core temperature. A static mixer can reduce that variation to less than 5°F.

– Dan Smith, PSI

Return to [Extrusion Hints](#)

Some of the icons were created by [FamFamFam](#) .