

Table of Contents

I. Introduction – Basics of Extrusion Troubleshooting – Russ Gould	I-1
The Value of Efficient Troubleshooting	I-1
Summary of Key Elements	I-2
Understanding the Whole Process	I-2
Personality Traits of a Good Troubleshooter	I-3
Defining the Problem	I-4
Troubleshooting Tools	I-4
Special Troubleshooting Tools	I-6
Process Analysis	I-7
Form Hypothesis and Test Solutions	I-8
References	I-9
1. Single-Screw Extruders – William A. Kramer, Edward L. Steward	1-1
1.1 Extrusion History	1-1
1.2 Single-Screw Functional Description	1-2
1.2.1 Feeding and Solids Conveying	1-3
1.2.2 Melting Considerations	1-6
1.2.3 Melt Pumping	1-9
1.2.4 Mixing	1-10
1.2.5 Devolatilizing (Venting)	1-11
1.2.6 Melt Filtering	1-12
1.3 Single-Screw Physical Description	1-13
1.4 Screw Design	1-18
1.4.1 Screw Functional Requirements	1-19
1.4.2 Screw Types	1-20
1.4.2.1 Conventional Screws (Metering and Mixing)	1-21
1.4.2.2 Barrier Screws	1-23
1.4.2.3 Two-Stage Screws (Venting)	1-24
1.4.2.4 Screw Cooling Effects	1-25
1.4.3 Mixing Considerations and Mixing Devices	1-26
1.4.4 Scaling Screw Design and Extruder Performance	1-27
TROUBLESHOOTING GUIDE	1-28
References	1-33
2. Twin-Screw Extruders – Charles Martin	2-1
2.1 Introduction	2-1
2.2 General Characteristics of Twin-Screw Extruders	2-2
2.3 Electronic Drives Used for Twin-Screw Extruders	2-3
2.4 Twin-Screw Gearbox Design	2-4
2.5 Defining the Feeder System to the Twin-Screw Extruder	2-4

Table of Contents

2.6	High-Speed, Modular Twin-Screw Extruders Designed for Mixing and Devolatilizing	2-5
2.7	Low-Speed, Late-Fusion Twin-Screw Extruders Used Primarily for PVC Processing	2-8
2.8	Downstream Operations	2-11
2.9	Summary	2-11
	TROUBLESHOOTING GUIDE	2-12
	References	2-26
3.	Alternate Extrusion Systems – Allan L. Griff, John R. Wagner, Jr.	3-1
	Conical Counter-Rotating Twins (Allan L. Griff)	3-1
	Barrel-Screw Interaction	3-2
	Tandem Extrusion	3-3
	Vertical Extruders	3-3
	Multi-screw Extruders	3-4
	Planetary-Gear Extruders	3-4
	Continuous Mixer (John R. Wagner, Jr.)	3-6
	References	3-8
4.	Extrusion Control – Tim Fisher	4-1
4.1	Extrusion Parameters	4-1
4.1.1	Parameters Typically Controlled in Extrusion	4-1
4.1.2	Parameters Typically Monitored in Extrusion	4-2
4.1.3	Recommended Additional Parameters for Monitoring to Detect Problems Before Any Damage Occurs, Track for Maintenance Purposes, or Ensure Proper Process Conditions	4-2
4.2	General Background on Control System Approach/Architecture	4-2
4.2.1	Discrete Instruments	4-2
4.2.2	Discrete instruments with Consolidated HMI or Human/Machine Interface	4-3
4.2.3	PLC with HMI	4-3
4.2.4	Real-time Integrated Extrusion Control Systems	4-3
4.2.5	PC-based Control	4-3
4.3	Extrusion Temperature Control	4-3
4.3.1	Temperatures	4-3
4.3.2	Types of Output	4-7
4.4	Pressure Monitoring and Control	4-8
4.5	Speed	4-9
4.6	Feed Systems	4-11
4.7	Melt Pumps	4-11
4.8	Things to Consider in Selecting a Controller or Control System	4-12
	TROUBLESHOOTING GUIDE	4-13
	References	4-14
5.	Auxiliary Systems – Daniel Smith, Peter Stoughton, Chuck Morgan, Gary R. Hovis	5-1
5.1	Melt Pumps (Dan Smith)	5-1
	Application	5-2
	Designing the Gear Pump System	5-4
	Gear Pump Housing	5-4

Table of Contents

	Gear Design	5-4
	Bearing Design	5-6
	Pump Drive System	5-7
	Pump Control System	5-7
	Useful Equations	5-7
	TROUBLESHOOTING GUIDE	5-9
	References	5-9
5.2	Filtration (Dan Smith)	5-10
	Reasons for Filtration	5-10
	Application Factors	5-10
	Types of Filtration	5-11
	Helpful Equation	5-16
	TROUBLESHOOTING GUIDE	5-16
	References	5-17
5.3	Polymer Drying (Pete Stoughton)	5-18
	Why Dry Plastic Pellets Before Processing?	5-18
	Moisture Problems	5-18
	Non-Hygroscopic Polymers	5-19
	Hygroscopic Polymers	5-19
	The Dehumidifying Dryer	5-20
	Principles of Operation	5-21
	Regeneration Air Circuit	5-23
	Desiccant Cooling	5-24
	Desiccant Dryer Designs	5-24
	TROUBLESHOOTING GUIDE	5-28
	References	5-28
5.4	Resin Conveying Systems (Chuck Morgan)	5-29
	High-Volume Material Flow System Description/Applications	5-29
	Types of High-Volume Conveying Systems	5-30
	Systems for Pellets and Powder	5-31
	In-plant Material Distribution Systems	5-31
	Common Components	5-31
	Self-contained Loading Systems	5-32
	Electric Motor, Self-contained Loaders	5-32
	Compressed-air, Self-contained Loaders	5-33
	Three-phase, Self-contained Mini-systems	5-33
	Central Vacuum Loading Systems	5-34
	Typical Applications for Central Vacuum Conveying Systems	5-34
	Central Conveying Systems for Pellets	5-34
	Central Conveying Systems for Powder	5-35
	Common Conveying System Configurations for Extrusion	5-36
	Dehumidified Drying Systems	5-36
	Direct Feed Vacuum Receivers	5-36
	TROUBLESHOOTING GUIDE	5-37
	References	5-38
5.5	Volumetric and Gravimetric Blending (Gary R. Hovis)	5-39
	Feeders	5-39
	Blenders	5-39
	Volumetric or Gravimetric	5-40
	Comparison of Blenders	5-41

Table of Contents

	Extrusion Blending with Yield Control	5-41
	Analyzing the Potential Investment Payback	5-42
	Yield Control with Co-extrusion	5-43
	TROUBLESHOOTING GUIDE	5-44
	References	5-44
6.	Resin Processing Properties – Mark Spalding, Kun Sup Hyun, John Vlachopoulos	6-1
6.1	Introduction	6-1
	Physical Properties and Applications for Selected Resins	6-2
6.2	Additives	6-4
6.3	Physical Properties Related to Processing	6-5
6.3.1	Bulk Density	6-6
6.3.2	Coefficients of Dynamic Friction and Shear Stress at the Interface	6-8
6.3.3	Melting Flux	6-11
6.3.4	Melt Density	6-12
6.3.5	Heat Capacity and Thermal Conductivity	6-13
6.3.6	Troubleshooting Using Resin Physical Property Data	6-14
6.3.7	Concluding Remarks	6-16
6.4	Rheology	6-16
6.4.1	Viscosity and Melt Flow Index	6-16
6.4.2	Extensional Viscosity and Melt Strength	6-20
6.4.3	Normal Stresses	6-21
6.4.4	Stress Relaxation and Dynamic Measurements	6-22
6.4.5	Constitutive Equations	6-25
6.4.6	Troubleshooting With The Help of Rheology	6-26
6.4.7	Concluding Remarks	6-26
	References	6-26
7.	Performance Characterization – John R. Wagner, Jr.	7-1
7.1	Introduction	7-1
7.2	Single-Screw – New System	7-1
7.3	Single-Screw – Existing System	7-6
7.4	Twin-Screw – New System	7-7
7.5	Further Optimization	7-12
	TROUBLESHOOTING GUIDE	7-12
	References	7-12
8.	Computer Aided Analysis and Design – John Vlachopoulos, David Strutt	8-1
8.1	Introduction	8-1
8.2	Mathematical Modeling and Numerical Methods	8-1
8.2.1	Finite Differences (FD)	8-2
8.2.2	Finite Elements (FE)	8-3
8.2.3	Flow Analysis Networks (FAN)	8-3
8.3	Molten Polymer Flows Through Dies	8-4
8.4	Single-Screw Extrusion	8-5
8.5	Twin-Screw Extrusion	8-7
8.6	How to Use Flow Analysis Software	8-8
8.7	Artificial Intelligence Methods	8-8

Table of Contents

8.8	Fault Diagnosis and Troubleshooting	8-9
8.9	Concluding Remarks	8-10
	References	8-10
9.	Extrusion Compounding – Chan I. Chung, David Todd, Chris Case	9-1
9.1	Introduction to Extrusion Compounding (Chan Chung)	9-1
9.1.1	Compounding, Miscibility and Compatibility	9-1
9.1.2	Types or Categorization of Mixing	9-1
9.1.3	Types of Flow	9-2
9.1.4	Characterization and Observation of Mixing	9-3
9.1.5	Feeding Methods	9-4
	TROUBLESHOOTING GUIDE	9-5
	References	9-6
9.2	Single-Screw Compounding (Chan Chung)	9-7
9.2.1	Mechanisms in Single-Screw Extruders	9-7
	References	9-7
9.2.2	Mixing Screws	9-7
9.2.3	Dynamic Mixers	9-8
9.2.4	Static Mixers	9-9
	TROUBLESHOOTING GUIDE	9-10
	References	9-10
9.3	Twin-Screw Compounding (David Todd)	9-11
9.3.1	Overview	9-11
	References	9-11
9.3.2	Types of Twin-Screw Compounders	9-12
9.3.3	Pretreatment	9-13
9.3.4	Feeding and Metering	9-14
9.3.5	Melting	9-14
9.3.6	Mixing	9-14
9.3.7	Reacting	9-16
9.3.8	Venting	9-16
9.3.9	Pressure Generation	9-17
9.3.10	Useful Equations	9-17
9.3.11	TROUBLESHOOTING GUIDE	9-19
	References	9-19
9.4	Pelletizing (Chris Case)	9-20
9.4.1	Introduction	9-20
9.4.2	Equipment	9-20
9.4.3	Die Design	9-24
9.4.4	Cooling	9-25
	TROUBLESHOOTING GUIDE	9-25
	References	9-27
10.	Pipe and Tubing Extrusion – Paul Hendess, Robert Bessemer	10-1
10.1	Die Design (Paul M. Hendess)	10-1
10.1.1	Introduction	10-1
10.1.2	Basic Design Characterization	10-2
10.1.3	Design Considerations	10-5
10.1.4	Temperature Measurement and Control	10-10

Table of Contents

10.1.5	Polymer Considerations	10-11
10.1.6	Polymer Interactions and Flow Concerns	10-13
	TROUBLESHOOTING GUIDE	10-21
10.1.7	References	10-25
10.2	Vacuum Sizing (Robert S. Bessemer)	10-25
10.2.1	Vacuum Technology	10-25
10.2.2	Methods of Creating Vacuum	10-26
10.2.3	Vacuum Control Systems	10-28
10.3	Pullers and Their Effect on Precision	
	Tubing Extrusion (Robert S. Bessemer)	10-30
10.3.1	Drive Systems	10-30
10.3.2	Belt Types and Applications	10-31
10.3.3	Cleated Pullers	10-32
10.4	Cutoff (Robert S. Bessemer)	10-32
10.5	Troubleshooting Downstream Extrusion Systems	10-36
	TROUBLESHOOTING GUIDE	10-36
11.	Blown Film Extrusion – Thomas I. Butler	11-1
	Introduction	11-1
	Process Control	11-3
	Extruder Type	11-3
	Output Rate	11-4
	Blown Film Die	11-6
	Co-extrusion	11-7
	Surface Melt Fracture (Sharkskin)	11-8
	Bubble Forming	11-8
	Air Ring	11-10
	High Stalk Process	11-12
	Collapsing	11-12
	Film Properties	11-13
	Film Property Test Methods	11-14
	TROUBLESHOOTING GUIDE	11-15
	References	11-20
12.	Cast Film and Sheet Extrusion – Jan Ivey	12-1
	Cast Film	12-1
	Co-extrusion	12-3
	Neck-in	12-6
	Pinning Methods	12-7
	Chill Roll Temperature	12-9
	TROUBLESHOOTING GUIDE	12-10
	References	12-12
13.	Extrusion Coating – Jim Cooper	13-1
	Introduction	13-1
	Overview for Troubleshooting Extrusion Coating	13-1
	Extrusion Coating Overview	13-1
	Control Parameters	13-2
	Problem Solving for Extrusion Coatings	13-3
	Adhesion	13-4

Table of Contents

Voids	13-6
Pinholes	13-6
Gauge Variances	13-7
Gels and Oxidation	13-8
“Applesauce”	13-9
Molten Curtain Breaks	13-10
Poor Heat Sealing	13-10
Glossary of Terms, Extrusion Coating	13-12
TRUBLESHOOTING GUIDE	13-13
References	13-16
14. Wire and Cable Processes – Christine Ronaghan	14-1
14.1 Applications	14-1
14.2 Payoff	14-2
14.3 Preheat	14-3
14.4 Extruder	14-3
14.5 Crosshead	14-4
14.6 Cooling Trough	14-6
14.7 Capstan	14-7
14.8 Take-Up	14-7
14.9 Quality/Process Control	14-7
TRUBLESHOOTING GUIDE	14-7
References	14-8
15. Monofilament Extrusion – Dr. John Hagewood	15-1
Applications	15-1
Polymers and Their Characteristics	15-1
Polymer Conditioning	15-2
Melt Extrusion	15-2
Metering Pumps	15-3
Spin Head	15-3
Bicomponent or Co-extruded Fibers	15-3
Quenching	15-4
Stretching	15-4
Heat Setting	15-5
Winding	15-5
Mathematical Modeling	15-5
TRUBLESHOOTING GUIDE	15-7
References	15-7
16 Profile Extrusion – Dan Cykana	16-1
16.1 Overview	16-1
16.2 Extrusion Line Layout	16-1
16.3 Extruder Requirements	16-3
16.4 Tooling Nomenclature	16-4
16.5 Die Design	16-5
16.6 Processing	16-6
16.7 Die Design and Balancing	16-8
TRUBLESHOOTING GUIDE	16-9
References	16-10

Table of Contents

17. Co-extrusion – Gary Oliver	17-1
History	17-1
Co-extrusion Considerations	17-3
Problems and Troubleshooting	17-3
TROUBLESHOOTING GUIDE	17-7
References	17-8
18. Reactive Extrusion – Carl G. Hagberg	18-1
18.1 Introduction	18-1
18.2 Brief History of REX Technology	18-1
18.3 Types of REX Processes	18-3
18.3.1 Controlled Degradation of Polymers	18-3
18.3.2 Grafting Monomers Onto Polymers	18-3
18.3.3 Functional Group Modification	18-5
18.3.4 Alloys and Blends of Two Polymers	18-6
18.3.5 In-situ Polymerization	18-6
18.3.6 Dynamic Vulcanization	18-8
18.4 Twin-Screw Extruders for Reactive Extrusion	18-8
18.4.1 CRNI Twin-Screw Extruder Characteristics	18-9
18.4.2 CRNI Advantages and Disadvantages for REX Processes	18-11
18.4.3 Co-rotating Intermeshing (CI) Twin Screw Extruder Characteristics	18-11
18.4.4 Co-rotating Intermeshing Advantages and Disadvantages for REX Processes	18-12
18.5 Extruder Overview	18-13
18.6 Commercial REX Extruder Applications	18-13
18.6.1 Grafting of Vinyl Siloxane	18-13
18.6.2 Anionic Polymerization of Caprolactam	18-13
18.6.3 Functional Group Modification	18-14
18.6.4 Polymer Alloys and Blends	18-15
18.7 Future Trends in Extruder Reactors	18-15
TROUBLESHOOTING GUIDE	18-16
References	18-18
19. Scrap Reclaim in the Extrusion Process – George Tedder	19-1
19.1 General Introduction	19-1
19.2 Reclaiming High-Bulk-Density Scrap	19-2
19.2.1 Handling High-Density Scrap and Feeding It to Size-Reduction Equipment	19-2
19.2.2 Granulator Cutting-Chamber Design for High-Density Scrap	19-3
19.2.3 Granulator Rotor Design for High-Density Scrap	19-4
19.2.4 Granulator Knife Design for High-Density Scrap	19-4
19.2.5 Feeding the Extruder With Size-Reduced High Density Scrap	19-5
19.3 Reclaiming Low-Bulk-Density Scrap	19-5
19.3.1 Handling Low-Density Scrap and Feeding it to Size-Reduction Equipment	19-5
19.3.2 Granulator Cutting-Chamber Designs for Low-Density Scrap	19-7
19.3.3 Granulator Rotor Design for Low-Density Scrap	19-7
19.3.4 Granulator Knife Design for Low-Density Scrap	19-8
19.3.5 Feeding the Extruder with Size-Reduced Low-Density Scrap	19-8
19.4 Reclaiming Other Extruded Scrap Materials	19-10

Table of Contents

19.4.1	Extrusion-Coating Scrap	19-10
19.4.2	Monofilament and Other Fiber Scrap	19-10
19.4.3	Wire-Coating and Cable Scrap	19-10
19.5	The Future of Scrap-Reclaim Equipment and Processes	19-11
	TROUBLESHOOTING GUIDE	19-11
	References	19-13
20.	Good Extrusion Practices – Allen L. Griff	20-1
20.1	The 10 Key Principles of Extrusion	20-1
1.	The Mechanical Principle	20-1
2.	The Thermal Principle	20-1
3.	The Need for Speed Reduction	20-2
4.	The Feed is the Coolant	20-2
5.	Stick to the Barrel and Slip on the Screw	20-3
6.	Material is the Biggest Cost	20-4
7.	Power Costs are Relatively Unimportant	20-4
8.	Pressure at the Screw Tip is Important	20-4
9.	Output is Displacement of Last Flight, \pm Pressure Flow \pm Leakage	20-5
10.	Shear Rate is Important, as Viscosity Depends Upon It	20-5
11.	The Motor Always Opposes the Barrel Temperature Controls (The Eleventh Law)	20-5
20.2	The Vital Signs – Follow Them All The Time	20-5
20.3	Extrusion Problems & Solutions	20-7
	References	20-12
Appendix 1	Glossary	Appendix 1-1
Appendix 2	Unit Conversion Factors	Appendix 2-1
Appendix 3	Useful Equations with Worked Out Examples	Appendix 3-1
Appendix 4	Useful Websites	Appendix 4-1
Appendix 5	Typical Processing Data	Appendix 5-1
Appendix 6	Author Biographies	Appendix 6-1

